## **Field Note Record**

| Contract No. Station |      | Mile/Line: | C/S               | C/S  |               |                     |  |  |  |
|----------------------|------|------------|-------------------|------|---------------|---------------------|--|--|--|
| 009359 Section 2     |      |            | I-82              |      |               |                     |  |  |  |
| Staked by            | Da   | ate        | Work Started Date |      | Work Complete | Work Completed Date |  |  |  |
| SURVEY               |      |            | 6/6/2019          |      |               |                     |  |  |  |
| 6/6/2019             |      |            |                   |      |               |                     |  |  |  |
| Calculated by        | y Da | te         | Checked by        | Date | Inspector     | Date                |  |  |  |
| Scott Busby          |      |            | E. Knudson        |      | Scott Busby   | 9/5/19              |  |  |  |
| 9/5/2019             |      |            | 9/10/2019         |      |               |                     |  |  |  |

## ITEM NO. 15 Section 2 - I-82 Umatilla to Ellensburg BEAM GUARDRAIL TYPE 31

Est.#6

## **Group Number 18**

6/20/2019 - I-82

- Station MP 97.16 Q1 Exit 96 on ramp 0.10 RT EB Sheet 4 Install **37.5 LF** of Beam Guardrail Type 31
- 37.5/6.25 = 6 Total of **6** wood posts
- 8 steel post (Typ.)

Note:

Measured by wheel and counted

| Item Num | n Material Brand<br>Name/Model Type                     |                                  | Manufacturer                   |      |                 | odel Type | RAMS/QPL<br>e Ref. No. |    | Appr/Ac<br>Code | Bas                                    | Basis of Accept  |      |  |
|----------|---|----------------------------------|--------------------------------|------|-----------------|-----------|------------------------|----|-----------------|--|--|------|--|
| 015.02   | Beam Guardrail Thrie<br>Beam Elements and<br>Components | Trinity Highway Products,<br>LLC |                                |      | QPL-0001        |           |                        | )1 | 2215            | / Mfr. Cert. per Stnd.<br>Spec. 1-06.3 |  |      |  |
| 015.03   | Beam Guardrail Wood Post<br>and Blocks                  | Superior Wood Treating           |                                |      |                 |           | QPL-000                | )5 | 2550            | or G<br>and<br>Trea<br>Env             | Lumber Grading Stamp<br>or Grading Certificate<br>and Certificate of<br>Treatment. (If Aquatic<br>Envir. Std. Spec. 9-09.3<br>(1) Applies) |      |  |
| 015.04   | Beam Guardrail Steel Post and Blocks                    | Trinit<br>LLC`                   | Trinity Highway Products, LLC` |      |                 |           | QPL-000                | )2 | 2215            |  | Mfr. Cert. per Stnd.<br>Spec. 1-06.3   |      |  |
| Item     | Item Description  | Grp                              | Date Work                      | Unit | Quantity Ledger |           | Posted E               |    | Ву              | Che                                    | cked By  | Est. |  |
| Num      |   |                                  | Complete                       |      |                 | Entry No  | · Init.                |    | Date            | Init.                                  | Date   | No.  |  |
| 0015     | BEAM GUARDRAIL TYPE 31                                  | 18                               | 9/5/2019                       | L.F. | 37.5            | 376       | EK                     | 11 | /25/19          |  |  | 8    |  |

## **Attachments**



Things to do 82-2.xlsx Microsoft Excel Worksheet 409 KB

DOT Form IP 422-635ER EF Revised 4/2009